



# LEED 2009 for Existing Buildings: Operations & Maintenance

## IEQ CREDIT 1.3: INDOOR AIR QUALITY BEST MANAGEMENT PRACTICES INCREASED VENTILATION

Project #

All fields and uploads are required unless otherwise noted.

### THRESHOLD ATTEMPTED

Points Attempted: 1

### ALL OPTIONS

All linked fields in this form must be consistent with IEQp1: Minimum Indoor Air Quality Performance and are read-only. To modify this information, please revisit IEQ Prerequisite 1.

Select all that apply to the project building:

- ☒ The project building is mechanically ventilated, in part or in whole.
- ☐ The project building is naturally ventilated, in part or in whole.

### MECHANICAL VENTILATION

Select all that apply to the project building:

- ☒ **Case 1.** One or more AHUs are able to meet the ASHRAE Standard 62.1-2007 outdoor air requirement.
- ☐ **Case 2.** One or more AHUs are unable to meet the ASHRAE Standard 62.1-2007 outdoor air requirement.

Compliance with IEQ Credit 1.3 documented for all mechanical ventilation AHUs from IEQp1:

Y

### ADDITIONAL DETAILS

- ☐ Special circumstances preclude documentation of prerequisite compliance with the submittal requirements outlined in this form.
- ☐ The project team is using an alternative compliance approach in lieu of standard submittal paths.

### SUMMARY

IEQ Credit 1.3: Indoor Air Quality Best Management Practices - Increased Ventilation Points Documented:

1

Check Compliance

Save Form